

13th July, 2024

1]
The Secretary
The Calcutta Stock Exchange Limited
7, Lyons Range
Kolkata 700 001
Scrip code: 10023915

2]
Listing Department
National Stock Exchange of India Ltd.
Exchange Plaza, Bandra-Kurla Complex,
Bandra (E), Mumbai - 400 051
Scrip code: MAITHANALL

Sub: Disruption of Operation at Byrnihat Unit

Dear Sir/Madam,

We hereby inform you that due to fire, there has been severe damage to one furnace transformer installed at our Byrnihat Unit.

One of the two furnaces would remain in shutdown condition till furnace transformer is replaced.

The full damage is yet to be ascertained.

The said transformer is insured.

The event has occurred on 13th July, 2024 at 06:10 A.M.

The information has been provided under Regulation 30 read with Schedule III of the Securities and Exchange Board of India (Listing Obligations and Disclosure Requirements), Regulations, 2015 and Master Circular No. SEBI/HO/CFD/PoD2/CIR/P/2023/120 dated 11th July, 2023 of Securities and Exchange Board of India.

This is for your information and appropriate dissemination.

Thanking you,

Yours faithfully,

For Maithan Alloys Limited

Rajesh K. Shah
Company Secretary

cc: The Corporate Relationship Department
BSE Limited
1st Floor, New Trading Ring, Rotunda Building,
P.J. Towers, Dalal Street, Fort, Mumbai 400 001
Script Code: 590078